

DRAFT - DISCHARGE UPDATE REPORT

Project: Temple-Inland Bogalusa Mill
Project Location: Bogalusa, Louisiana
Report Prepared By: Ed Cote
Date: August 28, 2011
Status of Report: Complete as of 3:00 pm, August 28 pending additional analyses

Weather Conditions: AM: fair/sunny PM: fair/sunny
Temperature: Max. 97°F
Cloud Cover: (Yes) (No)
Precipitation: (Yes) (No)

Discharge:
Beginning Time: 7:00 am
Ending Time: 6:45 pm (Target)
Discharge Stoppage: Yes

Reason for Stoppage:

Concern with dissolved oxygen level at Wailkiah Bluff, 32 miles downstream.

Description:

Flow resumed after the dissolved oxygen climbed to over 5.5 mg/l at Wailkiah Bluff.

Activities, Remarks:

- Discharge began at 6:58 am from the west weir
- Flow stopped at 7:48 am
- Flow restarted at 11:35 am at approximately 3.15 MGD
- Outfall monitoring was conducted in accordance with approved plan
- pH of discharge was within acceptable range
- ARCADIS assisted Temple-Inland with weir adjustments to maintain target flow

Problems/Deficiencies/Corrective Actions:

- None

Samples Taken / Results:

- Samples collected per frequencies indicated in Table 1 of approved Discharge Plan and results (to time indicated in above status) presented in attached table.

Calibration Records on Field Testing Equipment

- Outfall online pH and conductivity meters calibrated by Temple-Inland
- EBS sampling meters calibrated prior to start of discharge

Oversight/Visitors

- LDEQ representatives on site
- ISCO flow meter vendor representative
- EBS Sampling Laboratory